

# FC-USB Rev 1.3

## Revision notes

1. I had a mistake in the USB signals (swap) between U6 and U7

ZZ1

P/N = 188Z10030

PARSER\_VERSION\_1.0

LBL1

P/N = 374P07P14W

15x7mm Barcode

PCB1


PCB, FC-USB, Rev 1.3


LBL2

P/N = 374F13P20C


White/Polyester

### Revision EEPROM






		CompuLab Ltd. (972) 4 8290100 P.O.Box 66 Nesher 36770, Israel All Right reserved. Unauthorized duplication prohibited	
		Size A	Rev 1.1
Title INDEX		Document Number: 188Z10031	
Date: Sunday, August 11, 2019		Sheet 1 of 2	

# PCB EDGE CONN PADS (M.2 Key E)



# M.2 Key E, WiFi & BT



WRONG SIGNALS FROM SBC-APL  
RN - PROVISION FOR FUTURE DESIGN  
Pin 58, 60, 62, 64  
Those pins were dedicated for I2C in M.2 1.0  
but actually not used in StP.  
In new M.2 for 2015 it is used, serves as ISH  
UART,  
and its voltage level is 1.8 V  
ISH functionality can be used for future advanced  
capabilities  
of low power operation.

